



Kentronics  
1467 Bribie Island Road  
Ningi, Qld, 4511

ABN: 14 857 805 435

Ph: 07 5429 5363  
Fax: 07 5429 5364  
Mobile: 0417 377 480  
Email: [kenton@kentronics.com.au](mailto:kenton@kentronics.com.au)

## Eclipse Head Error Codes

Eclipse error codes are representational of a number flashing repeatable in the Dollars (\$) Display

ERROR 1 – Pulser Error. Power Cycle the head to reset. If error reoccurs replace head.  
ERROR 2 – System Error. Power Cycle the head to reset. If error reoccurs replace head.  
ERROR 3 – Price Change

The following are Batchen Head (LPG) Errors only

ERROR 14 – Temp Probe Error. No Probe detected  
ERROR 34 – Temp Board Error. Power Cycle the head to reset. If error reoccurs replace head.  
ERROR 54 – Temp Board Error. Power Cycle the head to reset. If error reoccurs replace head.